

01/23/89 11:04:40

TE REPORT

**DRAFT**

PAGE 1

SITE NO: 104 SITE NAME: Columbia Steel/Joslyn Sludge Pond

ALIASES: Columbia Steel Casting Co., Inc.

SITE ADDRESS: COUNTY: MULT STATUS: U REGION: NW

10425 N. Bloss Avenue  
Portland, OR 97203

DEQ CONTACT:

Take Columbia Blvd west of I-5 to Macrum Ave. Turn right and go approximately 5 blocks.

SITE CONTACTS: SIC CODES: 2491 3532

Unknown

CERCLIS ORD#:

DEQ PROGRAMS: None Listed

CONFIRMED RELEASE?	YES	
EVIDENCE VERIFIED?	YES	TYPE: 3
ON INVENTORY?	NO	
SPILL?	NO	
COMPLAINT?	NO	
PRIOR VISIT?	NO	
SOME REMEDIAL ACTION?	NO	
ADJACENT PROPERTY?	NO	

SIZE: 27.6 TNSHP: 1N RANGE: 1E SECT: 06

TAX LOTS: 7,118,122

**\*\*\* FACILITY INFORMATION \*\*\***

**FACILITY DESCRIPTION:**

Steel casting / Joslyn - Pole treating operation  
Public/private not indicated

WASTE MGMT UNIT	QTY	COMMENTS
-----------------	-----	----------

None Listed

**\*\*\* HAZARDOUS SUBSTANCES/WASTE TYPES \*\*\***

possible oil and creosote

USEPA SF



1495066

SITE NO: 104 SITE NAME: Columbia Steel/Joslyn Sludge Pond

\*\*\* CONTAMINATION INFORMATION \*\*\*

A storm drain discharging to a pond located on private property was observed discharging an oily chemical substance. Follow-up investigation found small amounts of oil and creosote-like materials flowing from the drain. Flow was intermittent and not immediately discovered. Subsequent investigation indicates the presence of an abandoned wood treating sludge pond adjacent to the drain.

\*\*\* OTHER INFORMATION \*\*\*

Regional investigation indicates the presence of an abandoned wood treating sludge pond.

\*\*\* POTENTIAL RESPONSIBLE PARTIES \*\*\*

PRP NO. 1 PRP NAME: Columbia Steel Casting Co., Inc. PHONE:  
AFFILIATION: Legal Owner STATUS: Current  
Columbia Metal Casting Co., Inc.  
P.O. Box 03095  
Portland, OR 97203

PRP NO. 2 PRP NAME: Joslyn Manufacturing PHONE:  
AFFILIATION: Generator STATUS: Current  
Joslyn Manufacturing

\*\*\* INFORMATION AND DATA SOURCES \*\*\*

## INFORMATION REVIEWED:

Correspondence from Owner or Operator

## DATA SOURCES:

Abandoned Haz Waste Site notebook

01/23/89 11:05:02

TE REPORT

PAGE 3

SITE NO: 104 SITE NAME: Columbia Steel/Joslyn Sludge Pond

\*\*\* HAZARDOUS SUBSTANCES \*\*\*

SUBSTANCE NAME: pentachlorophenol

DATE RELEASED: Unknown

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC:	Groundwater	8,300 ppb
	Soil	2,100 ppm

possible groundwater contamination

DATA SOURCES: Abandoned Haz Waste Site Notebook

SUBSTANCE NAME: toluene

DATE RELEASED:

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC:	Groundwater	440 ppb
	Soil	183 ppm

SUBSTANCE NAME: naphthalene

DATE RELEASED:

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC:	Groundwater	12,000 ppb
	Soil	6.6 ppm

01/23/89 11:05:15

IE REPORT

PAGE 4

SITE NO: 104 SITE NAME: Columbia Steel/Joslyn Sludge Pond

\*\*\* MANNER OF RELEASE \*\*\*

Abandoned

\*\*\* STATUS OF REMOVAL OR REMEDIAL ACTION \*\*\*

Columbia Steel has hired consultants to access the problem.

REMEDIAL ACTION CODES ASSIGNED FOR LEGISLATIVE REPORT:

RPIC DEQ Oversight of or Technical Assistance to Responsible Party Investigation, Cleanup,

PREPARED BY: Michael Zollitsch

ORIGINATION DATE: 03/29/88

LAST MODIFIED BY: Alice Larsen

MODIFICATION DATE: 12/30/88

LAST UPDATED: 12/30/88 14:25:32